

FORM R-1 REPORT OF REPAIR

(Authorized	Rep.	initials)

	in accordance with provisions of the National Board Inspection Code		- 1 - 14 1 1 (120 - 1) 1 1 1 1 1 1 1 1 1
		(Inspectors i	initials)
	WORK PERFORMED BY. Tiger Industries, Inc.	(Form "R" Re	egistration no.)
1.	WORK PERFORMED BY: (name of repair organization)	(P.O. no., job	no., etc.)
	8909 JACKRABBIT RD, SUITE B HOUSTON, TX 77095		
	(address)		
2.	OWNER: Tiger Industries, Inc.		
	8909 JACKRABBIT RD, SUITE B HOUSTON, TX 77095		
	(address) Wyoming		
3.	LOCATION OF INSTALLATION: (name)		
	(address)		
4.	ITEM IDENTIFICATION: Air Cooled Heat Excha NAME OF ORIGINAL MANUFACTURER: Happy Division, T	herma Te	ch., Inc.
	(boiler, pressure vessel, or piping)		4000
5.	IDENTIFYING NOS: 4525-1-1B 2294	ath au	1986 (year built)
2	2019	other)	(year built)
6.	NBIC EDITION/ADDENDA: (edition) (addenda)		
	Original Code of Construction for Item: ASME Section VIII, Division I 1983		
		/ addenda)	
	Construction Code Used for Repair Performed:	addenda)	
_	REPAIR TYPE: welded araphite pressure equipment FRP pressure equipment DOT		
8.	DESCRIPTION OF WORK: Form R-4, Report Supplementary Sheet is attached (NB-403) is (use Form R-4, if necessary))	s attached	
	Increased Outlet Nozzle Size to 6" to Match Inlet Nozzle Size.		
	Hydro-Static 390 260		
	Hydro-Static (Liguid, Pneumatic, Vacuum, Leak) Pressure Test, if applied 390 psi MAWP 260		psi
9.	REPLACEMENT PARTS: (Attached are Manufacturer's Partial Data Reports or Form R-3's properly completed for the following ite	ms of this rep	ort):
	(name of part, item number, data report type or Certificate of Compliance, mfg's. name and identifying stamp)		
10.	REMARKS:		
	1		3

(Form "R" Registration no.) 190608

(P.O. no., job no., etc.)

CERTIFICATE OF COMPLIANCE				
Austin Karl , certify that to the best of my knowledge and belief the statements made in this report are correct and that all material, construction, and workmanship on this Repair conforms to the <i>National Board Inspection Code</i> . National Board "R" Certificate of Authorization No. R-8878 Expiration date: October 26, 2024				
Repair Organization: Tiger Industries, Inc.				
Signed: (authorized representative) Date: 3-31-22				
CERTIFICATE OF INSPECTION				
Inspectors and certificate of competency, where required, issued by the Jurisdiction of TX and employed by TUV Rheinland AIA Services of Houston, TX have inspected the work described in this report on March 31st and state that to the best of my knowledge and belief, this work complies with the applicable requirements of the National Board Inspection Code. By signing this certificate, neither the undersigned nor my employer makes any warranty, expressed or implied, concerning the work described in this report. Furthermore, neither the undersigned nor my employer shall be liable in any manner for any personal injury, property damage, or loss of any kind arising from or connected with this inspection. Commissions: (National board and Jurisdiction no. including endofsement) Signed: (Inspector) Date: 3-31-22				