NB-66, Rev. 16, (02/04/21)

FORM R-1 REPORT OF REPAIR

in accordance with provisions of the National Board Inspection Code



1	WORK DEDECORMED BY. Tiger Industries, Inc.				(Form "R" 190611	Registration no.)
1.	WORK PERFORMED BY: (name of repair organization)				(P.O. no., jo	ob no., etc.)
	8909 JACKRABBIT RD, SUITE B HOUSTON	N, TX 77095				
	(address)					
	OWNER: Tiger Industries, Inc.			2		
۷٠	(name)			(1)		
	8909 JACKRABBIT RD, SUITE B HOUSTO	N, TX 77095				
	(address)					
3.	LOCATION OF INSTALLATION: Wyoming	_				
	(name)					
	(address)			Haran Divis	: Th T	ala laa
4.	ITEM IDENTIFICATION: Air Cooled Heat Excha	NAME OF ORIGINAL	MANUFACTURER:	Happy Divis	sion, Therma Te	ecn., inc.
	(boiler, pressure vessel, or piping)					
_	4525-1-1C	2295				1986
٥.	IDENTIFYING NOS: (mfg. serial no.)	(National Board no.)	(jurisdiction	no.)	(other)	(year built)
2	2019					
5.	NBIC EDITION/ADDENDA: (edition)	(addenda)	29	* T	C1 11	
	Original Code of Construction for Item:	ction VIII, Division	l =	19	983	
	(name / secti	on / division)	T - 100		(edition / addenda)	
	Construction Code Used for Repair Performed: ASN	ME Section VIII, Div	vision I	2019		
	*	(name / section / division)		. (edition / addenda)	
7	REPAIR TYPE: welded graphite pressur	ro oquipment	FRP pressure equ	inment [DOT	
/.	REPAIR 1 TPE: Welded	re equipment —	r nr pressure equ			
8.	DESCRIPTION OF WORK: Form R-4, Report Supplementary Sheet is attached FFSA Form (NB-403) is attached (use Form R-4, if necessary))					
		Matala Imlat Na	la Ci-a			
	Increased Outlet Nozzle Size to 6" to	Match Inlet No	zzie Size.			
	Hydro-Static Procesure Test if applie	390	80.500	MANUE 260		
	(Liquid, Pneumatic, Vacuum, Leak) (Liquid, Pneumatic, Vacuum, Leak)	d	psi	MAWP		psi
9.	REPLACEMENT PARTS: (Attached are Manufacturer's Par	rtial Data Reports or Forn	n R-3's properly comp	oleted for the follow	wing items of this re	port):
	(name of part, item number, data report type or Certificate of Co	mpliance, mfg's. name and i	dentifying stamp)			
10	REMARKS:					
						-

100

(Form "R" Registration no.) 190611

(P.O. no., job no., etc.)

CERTIFICATE OF COMPLIANCE						
Austin Karl, certify that to the best of my knowledge and belief the statements made in this report are correct and that all material, construction, and workmanship on this Repair conforms to the National Board Inspection Code. National Board "R" Certificate of Authorization No. R-8878 Expiration date: October 26, 2024 Repair Organization: Tiger Industries, Inc. Signed:						
CERTIFICATE OF INSPECTION						
Inspectors and certificate of competency, where required, issued by the Jurisdiction of TX and employed by TUV Rheinland AIA Services of Houston, TX have inspected the work described in this report on November 8th , 2022 and state that to the best of my knowledge and belief, this work complies with the applicable requirements of the National Board Inspection Code. By signing this certificate, neither the undersigned nor my employer makes any warranty, expressed or implied, concerning the work described in this report. Furthermore, neither the undersigned nor my employer shall be liable in any manner for any personal injury, property damage, or loss of any kind arising from or connected with this inspection. Commissions: (National Board and Jurisdiction no including endors ment) Signed: (National Board and Jurisdiction no including endors ment)						