



NB-66, Rev. 16, (02/04/21)

FORM R-1 REPORT OF REPAIR

in accordance with provisions of the National Board Inspection Code



1.	WORK PERFORMED BY: Tiger Industries, Inc.	(Form "R" Registration no.)
	(name of repair organization) 8909 JACKRABBIT RD, SUITE B HOUSTON, TX 77095	(P.O. no., job no., etc.)
2.	OWNER: Tiger Industries, Inc.	
	(name) 8909 JACKRABBIT RD, SUITE B HOUSTON, TX 77095 (address)	
3.	LOCATION OF INSTALLATION: Texas (name)	
	(address)	
4.	ITEM IDENTIFICATION: Air Cooled Heat Excha (boiler, pressure vessel, or piping) NAME OF ORIGINAL MANUFACTURER: Fabsco, Inc.	
5.	IDENTIFYING NOS: 81-1742-2	1981
	(mfg. serial no.) (National Board no.) (jurisdiction no.) (oth NBIC EDITION/ADDENDA:	(year built)
	(edition) (addenda)	_ 8
	Original Code of Construction for Item:	ddanda)
	Construction Code Used for Repair Performed: ASME Section VIII, Division I 2021	idenda)
	(name / section / division) (edition / ad	denda)
7.	REPAIR TYPE: welded graphite pressure equipment FRP pressure equipment DOT	
8.	DESCRIPTION OF WORK: Form R-4, Report Supplementary Sheet is attached FFSA Form (NB-403) is a (use Form R-4, if necessary))	ittached
	Inlet Nozzles upgraded to match the existing Outlet Nozzle at 6" 300# RF. Another 6" Outlet Nozzle added which matched the existing Outlet Nozzle.	
	Hydro-Static Procesure Test if applied 450	
	Pressure lest, if applied psi MAWP	psi
9.	(Liquid, Pneumatic, Vacuum, Leak) REPLACEMENT PARTS: (Attached are Manufacturer's Partial Data Reports or Form R-3's properly completed for the following items (name of part, item number, data report type or Certificate of Compliance, mfg's. name and identifying stamp)	psi s of this report):

¥ , j.:

(Form "R" Registration no.) 190431

(P.O. no., job no., etc.)

CERTIFICATE OF COMPLIANCE		
I, Austin Karl , certify that to the best of my knowledge and belief the statements made in this report are correct and that all material, construction, and workmanship on this Repair conforms to the <i>National Board Inspection Code</i> . National Board "R" Certificate of Authorization No. R-8878 Expiration date: October 26, 2024		
Repair Organization: Tiger Industries, Inc.		
Signed: (authorized representative)		
Date: 4-10-23		
CERTIFICATE OF INSPECTION		
Inspectors and certificate of competency, where required, issued by the Jurisdiction of TX and employed by TUV Rheinland AIA Services of Houston, TX 2023 and state that to the best of my knowledge and belief, this work complies with the applicable requirements of the National Board Inspection Code. By signing this certificate, neither the undersigned nor my employer makes any warranty, expressed or implied, concerning the work described in this report. Furthermore, neither the undersigned nor my employer shall be liable in any manner for any personal injury, property damage, or loss of any kind arising from or connected with this inspection. Commissions: (National Board of Boiler and Pressure Vessel TX 2023 and state the Undersigned Inspection Code. By signing this certificate, neither the undersigned nor my employer shall be liable in any manner for any personal injury, property damage, or loss of any kind arising from or connected with this inspection. Commissions: (National Board of Boiler and Pressure Vessel TX 2023 and state that to the David Inspection Code. By signing this certificate, neither the undersigned nor my employer shall be liable in any manner for any personal injury, property damage, or loss of any kind arising from or connected with this inspection. Commissions: (National Board of Boiler and Pressure Vessel (National Board of Boiler and Pressure Vessel (National Board of Boiler and Employed by TX All David Inspection of TX All Dav		